

Version 203 Update

1100R Series Wireless Repeaters are now being manufactured with Version 203 (1/10/25) firmware.

Improvements

Previously, the 1100R sent a **NOPWR** (no power) trouble message when powered on. This update lowers the low power threshold to 10.2 volts, so the 1100R powers up without indicating low power trouble.

Obtaining the New Firmware

1100R Wireless Repeaters with Version 203 firmware can be ordered by contacting DMP Customer Service at 1-866-266-2826 or by visiting buy.dmp.com.