Version 241 Update

Updated Version 241 firmware is now available for XT30/XT50, XTLplus, and XTLtouch Series.

Improvements

Previously, when the panel tried to communicate with the receiver and missed the check-in minutes for NET communication, the panel sent an S72 (Comm Trouble) message before the **FAIL TIME** minutes elapsed. This update allows the fail time minutes to pass before the panel detects a communication failure.

Obtaining the New Firmware

Firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or for download from DMP's Product Software Downloads.