

Version 241 Update

Updated Version 241 (11/18/24) firmware is now available for XR Series Control Panels.

Improvements

Rearm Delay Minutes

Previously, when accessing AX-Bus Doors, the Rearm Delay for Profiles would not exceed 255 minutes. Now, up to 720 minutes can be set for the Rearm Delay.

Integrator Connection

This update allows the integrator connection to function correctly for panel programming.

Obtaining the New Firmware

XR Series firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or for download from DMP's [Product Software Downloads](#).