

Version 186.1.0.1076 Update

Updated Version 186.1.0.1076 firmware is now available for 8860 Touchscreen Keypads.

Version 186.1.0.1076 is supported by XT30/XT50 and XR150/XR550 Series panels with firmware Version 231 or higher.

V-6000 Support Update

This update allows the 8860 keypad to display live video and video event clips from V-6000 Series Cameras.

Obtaining the New Firmware

Firmware updates are available on Dealer Admin (dealer.securecomwireless.com) and in the **Installer Options** menu on the keypad. Follow the instructions below to update the keypad firmware on Dealer Admin and at the keypad.



Note: This update could take several minutes. If you are updating from Dealer Admin, please refresh the page to verify that the keypad has checked in with its new version number.

Update the Keypad on Dealer Admin

1. Ensure that the keypad is connected to the Wi-Fi network before proceeding.
2. Navigate to Dealer Admin.
3. Select the user and system.
4. Next to the keypad name, select **Update**.

Update the Keypad in Installer Options

1. Ensure that the keypad is connected to the Wi-Fi network before proceeding.
2. Select **Options** from the Carousel menu, then select **Installer Options**.
3. Enter **3577** and enter **CMD**. Select **Check for Updates**. Follow the on-screen prompts.