

### Version 232 Date Code Update

Updated Version 232 (5/31/24) firmware is now available for download.

#### Affected Products

- DualCom
- CellComLTE
- PowerCom

#### Improvements

When a panic is initiated from a Vista series keypad, the keypad no longer temporarily ignores button presses.

Check-in messages sent over the primary and backup communication paths are no longer suppressed when check-ins are frequent, whereas previously, frequent check-in messages sent over the backup path were suppressed.

### Obtaining the New Firmware

COM Series firmware updates are available, free of charge, on Dealer Admin ([dealer.securecomwireless.com](https://dealer.securecomwireless.com)) or for download from DMP's [Product Software Downloads](#).