

Version 241 Update

Updated Version 241 (5/17/24) firmware is now available for XT30/XT50, XTLplus, and XTLtouch Series panels.

Improvements

Output Names Update

Wireless output names that are sent to 8860 Series Touchscreen Keypads via network communication will display properly on the keypad Attention List when the output goes into Low Battery, Trouble, or Missing.

Keyfob Names Update

Keyfob names that are sent to 8860 Series Touchscreen Keypads via network communication will display properly on the keypad Attention list when the keyfob goes into Low Battery or Missing.

User Code Update

When adding a user code to an 8860 Series Touchscreen Keypad for Bluetooth Disarming, the panel will send the correct number of digits to the keypad.

Obtaining the New Firmware

Firmware updates are available, free of charge, on Dealer Admin (dealer.securecomwireless.com) or for download from DMP's [Product Software Downloads](#).